


## 82.6 Flexible chain with bearing

- Main application : All kinds of transportation .
- Material: POM. Work temperature: -30°C to 90 °C
- Pin mat.: Stainless steel



sprocket ref. P58



parts ref. P306-332



wear strip ref. P355-359




chain guide ref. P343-354

Code	Width (mm)	Weight (Kg/m)	Backflex radius	Sideflex radius
82.6-CZ	82.6	1.4	120	200

## 82.6 Flexible chain with rubber and bearing

- Main application : All kinds of transportation .
- Material: POM. Work temperature: +1°C to +80 °C
- Pin mat.: Stainless steel



sprocket ref. P58



parts ref. P306-332



wear strip ref. P355-359



chain guide ref. P343-354

Code	Width (mm)	Weight (Kg/m)	Backflex radius	Sideflex radius
F82.6-CZ	82.6	1.5	120	200